

# Volvo Engine broken Engine broken

## General characteristics

|                            |                 |
|----------------------------|-----------------|
| Brand                      | Volvo           |
| Subcategory                | Cab over engine |
| License plate              | BS-NT-26        |
| Meter reading              | 868.489km       |
| Year of construction       | 2007            |
| Date of first registration | 12-01-2007      |
| Condition                  | Used            |
| Fuel                       | Diesel          |
| Emission class             | Euro 5          |
| Reference                  | VH1123          |



## Properties

|                   |                   |
|-------------------|-------------------|
| Single weight     | 6.969kg           |
| Load capacity     | 11.631kg          |
| GVW               | 18.600kg          |
| Length            | 599cm             |
| Width             | 247cm             |
| Serial number     | YV2JL60A37B456876 |
| Cylinder capacity | 9.365cc           |

## Accessories

- Automatic

## Technical specifications

|                    |           |
|--------------------|-----------|
| Number of axes     | 2         |
| Axis configuration | 4x2       |
| Transmission       | Automatic |
| Assets             | 346hp     |